

CHANGE HISTORY FOR BDP-V6000

Ver 4.24

- ✓ Fix issue of cannot stop with the address that by RS-232C SM command, PL command.
- ✓ During a search by a RS-232C SL command, it was changed to output a screen before search.
- ✓ Enhances stability of Chapter Repeat

Ver 4.13

- ✓ When address assignment is Time by a RS-232C SE command, the still image has improved the deficiency which slips several frames
- ✓ The deficiency which may be unable to set up power-on start function has been improved.
- ✓ Enhances BD-ROM playability and stability of BD-Java playback
- ✓ Enhances stability of BD-LIVE functions
- ✓ Enhances stability of BD-R/BD-RE playback

Ver 4.03

- ✓ Original version